2904K-01

PROBLEM SYMPTOMS TABLE

Use the table below to help you find the cause of the problem. The numbers indicate the priority of the likely cause of the problem. Check each part in order. If necessary, replace these parts.

Symptom	Suspect Area	See page
Oil leak from rear differential	5. Oil level (Too high or wrong grade)	29–7
	6. Rear differential front oil seal (Worn or damaged)	29–8
	7. Side gear oil seal (Worn or damaged)	29–10
Noise in rear differential	Oil level (Low or wrong grade)	29–7
	2. Excessive backlash between pinion and ring gear	29–12
	3. Ring, pinion or side gears (Worn or chipped)	29–12
	4. Drive pinion bearing	29–12
	5. Side bearing (Worn)	29–12

2003 COROLLA MATRIX (RM940U)

Author: Date: 1744