

EMISSION CONTROL

SERVICE DATA

030PI-02

1ZZ-FE

Oxygen sensor Resistance	HT – +B	11 – 16 Ω
VSV for Pressure switching valve Resistance	at 20°C (68°F)	37 – 44 Ω
Vacuum switching valve No.1 Resistance	at 20 °C (68 °F)	27 – 33 Ω
Vacuum switching valve assy No. 1 Resistance	at 20°C (68°F)	25 – 30 Ω

2ZZ-GE

Oxygen sensor Resistance	HT – +B	11 – 16 Ω
VSV for Pressure switching valve Resistance	at 20°C (68°F)	37 – 44 Ω
Vacuum switching valve No.1 Resistance	at 20 °C (68 °F)	27 – 33 Ω
Vacuum switching valve assy No. 1 Resistance	at 20°C (68°F)	25 – 30 Ω