## FRONT SUSPENSION SYSTEM PROBLEM SYMPTOMS TABLE

2607R-03

Use the table below to help you find the cause of the problem. The numbers indicate the priority of the likely cause of the problem. Check each part in order. If necessary, replace these parts.

Symptom	Suspect Area	See page
	Vehicle (Overloaded)	_
Bottoming	2. Spring (Weak)	26–10
	3. Shock absorber (Worn)	26–10
	Tire (Worn or improperly inflated)	28–1
Sways/pitches  Front wheel shimmy	2. Stabilizer bar (Bent or broken)	26–22
	3. Shock absorber (Worn)	26–10
	Tire (Worn or improperly inflated)	28–1
	2. Wheel (Out of balance)	28–1
	3. Shock absorber (Worn)	26–10
	4. Wheel alignment (Incorrect)	26–6
		27–6
		27–7
	5. Ball joint (Worn)	26–20
	6. Hub bearing (Worn)	30–3
	7. Steering linkage (Loose or worn)	_
Abnormal tire wear	Tire (Worn or improperly inflated)	28–1
	2. Wheel alignment (Incorrect)	26–6
		27–6
		27–7
	3. Shock absorber (Worn)	26–10
	4. Suspension parts (Worn)	-

2003 COROLLA MATRIX (RM940U)

Author: Date: 1676