W/RECEIVER CONDENSER ASSY

ON-VEHICLE INSPECTION

550JI-0

- 1. INSPECT W/RECEIVER CONDENSER ASSY
- (a) If a fin of the w/receiver condenser assy is dirty, clean it with water and dry it with compressor air. **NOTICE:**

Do not damage the fin of the w/receiver condenser assy.

- (b) If a fin of the w/receiver condenser assy is bent, make it straight using a screwdriver or pliers.
- 2. INSPECT W/RECEIVER CONDENSER ASSY FOR LEAKAGE OF REFRIGERANT
- (a) Using a halogen leak detector, check pipe joints for gas leakage.
- (b) If gas leakage is detected in a joint, check the torque of the joint.

2003 COROLLA MATRIX (RM940U)

Author: Date: 2357